



Annexure - I (Pictorial Representation of Apartment Progress)


25-Dec-11




D - NAINITAL



B3 - Khandala



C3 - MUSSORIE





B2 - Darieling

25-Dec-11




C1 - SHIMLA







C4 - Munnar







Parapet Wall	OHT			LMR			
13th Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
12th Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
11th Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
10th Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
9th Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
8th Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
7th Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
6th Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
5th Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
4th Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
3rd Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
2nd Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
1st Floor Roof	F 3W	E 3E	D 1E		C 4W	B 3W	A 2E
Stilt Floor Roof							
Basement 1 Roof							
Plinth Beam							
Footings							

Works Completed by 01.01.2009

-  RCC Structure
-  Block Work


Works Done By IL&FS ECC

-  BLOCK WORK
-  PLASTERING
-  RCC STRUCTURE
-  BACKFILLING





C3 - MUSSORIE





14-Oct-11




Works Completed by 01.01.2009

-  RCC Structure
-  Block Work

Works Done By IL&FS ECC


-  BLOCK WORK
-  PLASTERING
-  RCC STRUCTURE
-  BACKFILLING

B2 - Darjeeling





B1 - Dalhousie





14-Oct-11



Works Completed by 01.01.2009

-  RCC Structure
-  Block Work



Works Done By IL&FS ECC

-  BLOCK WORK
-  PLASTERING
-  RCC STRUCTURE
-  BACKFILLING





C1 - SHIMLA


Parapet Wall	OHT		LMR			
13th Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
12th Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
11th Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
10th Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
9th Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
8th Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
7th Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
6th Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
5th Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
4th Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
3rd Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
2nd Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
1st Floor Roof	F 4W	E 5E	D 5E	C 4W	B 5W	A 4E
Stilt Floor Roof						
Basement 1 Roof						
Basement 2 Roof						
Plinth Beam						
Footings						

Works Completed by 01.01.2009


-  RCC Structure
-  Block Work

Works Done By IL&FS ECC





-  BLOCK WORK
-  PLASTERING
-  RCC STRUCTURE
-  BACKFILLING



Works Completed by 01.01.2009

-  RCC Structure
-  Block Work

Works Done By IL&FS ECC

-  BLOCK WORK
-  PLASTERING
-  RCC STRUCTURE
-  BACKFILLING

